

FORT WAYNE CAMPUS
2121 Lake Avenue
Fort Wayne, Indiana 46805

MARION CAMPUS 1700 E 38th Street Marion, Indiana 46953

GENERAL NOTES

- 1. THE CONTRACTOR SHALL PROVIDE ALL LABOR, MATERIALS, TOOLS, EQUIPMENT, AND COMPETENT SUPERVISION NECESSARY TO REPLACE, REPAIR, OR INSTALL VARIOUS DOORS AS SPECIFIED IN THIS PROJECT.
- 2. EXCEPT FOR THE B172/174 DOOR, ALL WORK SHALL BE PERFORMED DURING ADMINISTRATIVE HOURS (7:00AM 3:30PM WEEKDAYS EXCLUDING FEDERAL HOLIDAYS). DUE TO DINING TIMES IN BUILDING 174, THE B172/174 DOOR SHALL BE PERFORMED BETWEEN THE HOURS OF 7:00PM AND 6:00AM (MONDAY NIGHT FRIDAY MORNING) SO AS TO AVOID THE FLOW OF PATIENT TRAFFIC
- 3. AT THE CONCLUSION OF EACH WORK DAY, SITES SHALL BE CLEAN AND FREE OF DEBRIS. ADDITIONALLY, THE AREAS MUST BE SAFELY TRAVERSABLE DURING ADMINISTRATIVE HOURS.
- 4. THE CONTRACTOR SHALL BE RESPONSIBLE FOR FIELD VERIFYING ALL MEASUREMENTS.
- 5. ALL DEBRIS SHALL BECOME THE PROPERTY OF THE CONTRACTOR UNLESS OTHERWISE MARKED OR NOTED BY THE VA.
- 6. THE CONTRACTOR SHALL KEEP THE WORK SITE CLEAN AND FREE FROM OBSTRUCTIONS AT ALL TIMES. UPON FINAL CLEAN-UP, THE CONTRACTOR SHALL REMOVE ALL DEBRIS, RUBBISH, AND EXCESS MATERIAL FROM THE STATION
- 7. INSTALL SUFFICIENT WALL, FLOOR, AND CEILING PROTECTION TO EXISTING MATERIALS. IF EXISTING MATERIALS AND/OR FINISHES BECOME DAMAGED, CONTRACTOR SHALL REPAIR OR REPLACE AT HIS/HER OWN EXPENSE.
- 8. THE WORK PERFORMED SHALL MEET THE REQUIREMENTS OF THE LATEST EDITION OF NFPA 101 AND NFPA 80 AND DOCUMENTS REFERENCED THERE
- 9. EACH CONTRACTOR IS RESPONSIBLE TO PERFORM THEIR WORK IN ACCORDANCE WITH ALL FEDERAL AND OSHA REGULATIONS.
- 10. CONTRACTOR TO ACCOMPLISH WORK IN A MANNER THAT WILL DISTURB
 ADJACENT SITE AREAS AS LITTLE AS POSSIBLE.
 11. AT THE CONCLUSION OF EACH DOOR AREA. THE CONTRACTOR SHALL WIP
- 11. AT THE CONCLUSION OF EACH DOOR AREA, THE CONTRACTOR SHALL WIPE DOWN ALL SURFACES TO REMOVE DUST AND DIRT ASSOCIATED WITH DEMOLITION AND CONSTRUCTION.
- 12. WALL AND FLOOR PENETRATIONS THROUGH FIRE WALLS AND FLOORS ARE TO BE FIRE STOPPED.
- 13. THE TERMS PROJECT MANAGER, PROJECT ENGINEER, CONTRACTING OFFICER'S TECHNICAL REPRESENTATIVE (COTR), VA REPRESENTATIVE, AND RESIDENT ENGINEER (RE) ARE USED INTERCHANGEABLY THROUGHOUT THE SPECIFICATIONS AND DRAWINGS.






INDEX OF SHEETS:


GI001 COVER SHEET

S101 DOOR REPLACEMENT PLAN


610-10-109 REPLACE VARIOUS DOORS, B172/174 (PFI) BUILDINGS 172/174 (M), 138 (M), AND 1 (FW)

VA Northern Indiana Health Care System, Marion 1700 E 38th Street Marion, IN 46953





03/12/2012







FORT WAYNE CAMPUS

BUILDING 1 AUDITORIUM









REMOVE AND REPLACE (PROVIDE AND INSTALL) THE FOLLOWING UL

1.1. CRASH-BAR EGRESS INCLUDING SURFACE-MOUNTED VERTICAL

- 1.1.1. REPAIR ANY HOLES FROM EXISTING VERTICAL ROD SYSTEM
- PAINT DOOR TO MATCH EXISTING DOOR COLOR
- PAINT FRAME TO MATCH EXISTING FRAME COLOR

B1 (FW) BASEMENT STAIRWELL/RM 49 NOTES

FOR THE STAFF IN THE WAREHOUSE

AND DISPOSE OF AT PROPER LANDFILL.

(DOOR AND FRAME) (44" X 7'-0").

5.1. POSITIVE LATCHING

VA FORM 08-6231, OCT 1978

. INSTALL THE FOLLOWING HARDWARE

5.5. BUTT-HINGES SHALL BE NON-REMOVABLE

. PAINT DOOR AND FRAME TO MATCH EXISTING.

8. PROVIDE AND INSTALL FIRE DOOR SIGNAGE IN-01.05.

9. PROVIDE AND INSTALL WALL MOUNTED DOOR STOP.

DOOR AND FRAME ARE REMOVED, PROVIDE 2-HOUR FIRE RATED BARRIER. INTERIM LIFE SAFETY MEASURES WILL BE PUT INTO PLACE

THE EXISTING FIRE DOOR IS ASSUMED TO CONTAIN ASBESTOS. AS

SIDES OF THE DOOR TO PREVENT THE SPREAD OF DUST DURING

DEMOLITION OF THE EXISTING DOOR. IF SAW-CUTTING METHOD IS

USED, WET THE DEBRIS/DUST TO PREVENT THE SPREAD OF DUST


4. PROVIDE AND INSTALL 3 HOUR FIRE-RATED METAL DOOR ASSEMBLY

5.4. MORTISE LOCKSET (LOCKSET SHALL ACCEPT A 7-PIN CORE

6. FINISH WALL AROUND NEW DOOR TO PREVIOUS CONDITIONS

SEAL THE DOOR WITH 2 LAYERS OF 6-MIL POLY, LABEL AS ASBESTOS,

- PROVIDE AND INSTALL FIRE DOOR SIGNAGE IN-01.05.
- CONTRACTOR SHALL ASSURE THAT THE NEW DOOR HARDWARE WILL MAINTAIN THE RATING OF THE ENTIRE ASSEMBLY. CONTRACTOR SHALL ADJUST DOOR AND/OR HARDWARE TO MEET FIRE




B1 FW Auditorium


BUILDING 1 BASEMENT STAIRWELL/RM 49














1 Basement Stairwell/Rm 49

VA Northern Indiana Health Care System, Marion 1700 E 38th Street Marion, IN 46953

MOTORIZED DOOR OPERATOR DOOR CHIME/ INTERCOM COMBO

KEY-CORE AND MOTION SENSOR TO UNLOCK THE ELECTRO-MAGNETIC DOOR LOCK FOR NORMAL USE AND ACTIVATE AUTOMATIC DOOR DOOR CHIME/INTERCOM TO BE INSTALLED WHERE SHOWN. THE OTHER CHIME/INTERCOM TO BE INSTALLED WITHIN SPD AREA IN ROOM 6.

SINGLE OR DOUBLE AS

HEIGHT THICKNESS MATERIAL

7'-0" 0'-1 3/4" SC-WOOD

7'-0" 0'-1 3/4" STEEL

SC-WOOD

7'-0" 0'-1 3/4"

REQUIRED

ELECTRO-MAGNETIC DOOR LOCK TO BE TIED TO FIRE ALARM SYSTEM TO UNLOCK ON ALARM. REMOVE EXISTING EXIT LIGHT. CONNECT NEW LED EXIT LIGHTS TO EXISTING

Approved: Medical Center Director Daniel D. Hendee, FACHE Approved: Associate Director for Operations - Marion Helen Rhodes Approved: Project Director Approved: Engineering Service

MARION CAMPUS


B138 SPD (BASEMENT)

I. REMOVE WOOD FROM HEADER

- 2. MODIFY AND/OR INSTALL HEADER TO RECEIVE NEW 6070 FRAME. 3. INSTALL NEW 5/8" TYPE 'X' GWB OVER MODIFIED HEADER, BOTH SIDES.

- AND 1.5 HOUR FIRE-RATED FRAME (6070). DOORS SHALL INCLUDE QUARTER LIGHT GLAZING. THIS DOOR ASSEMBLY WILL BE CONSIDERED
- 7.2. ELECTRO-MAGNETIC LOCKS
- AUTOMATIC DOOR OPENERS (ONE FOR EACH DOOR)

- 13. BUILD NEW WALL AROUND NEW FRAME. WALL SHALL BE A SMOKE
- 15. FINISH WALL AROUND NEW DOOR TO MATCH EXISTING CONDITIONS 16. PAINT NEWLY CONSTRUCTED WALL TO MATCH EXISTING (DOVER
- 18. WOOD SPECIES AND FINISH SHALL MATCH EXISTING BASEMENT DOORS LIGHTS ON BOTH SIDES OF THE NEW DOUBLE DOORS (2 EXITS LIGHTS
- 20. ANCHOR NEW STUD THROUGH METAL PLATES ON BOTH SIDES. POWER FOR NEW DOOR HARDWARE SHALL BE FED FROM PANEL EBB IN ROOM 8 (APPROXIMATELY 32 FEET FROM DOOR ASSEMBLY



SEE D1 AND D2 FOR

DETAILS, SECTIONS, AND

B138 SPD DOUBLE EGRESS DOOR PLAN


NON-SPD SIDE

Scale: 1/4" = 1'-0"

SEE D1 AND D2 FOR

B172

DETAILS, SECTIONS, AND






B172/174



- REMOVED, THE NEW DOORS AND FRAME SHALL BE INSTALLED DURING THE SAME WORK SHIFT TO MAINTAIN BARRIER. PROVIDE AND INSTALL 1.5 HOUR FIRE-RATED, DOUBLE EGRESS DOORS AND 1.5 HOUR FIRE-RATED FRAME (7070). DOORS SHALL INCLUDE QUARTER LIGHT GLAZING.
- . INSTALL THE FOLLOWING HARDWARE: 3.1. POSITIVE LATCHING 3.2. CRASH-BAR EGRESS (VERTICAL ROD LATCHING LESS BOTTOM ROD)
- 3.4. HOLD-OPEN PLATES SHALL BE POSITIONED TO WORK WITH EXISTING HOLD-OPEN 3.5. UL LABELED MOP AND KICK PLATES - COLOR SHALL MATCH EXISTING
- 4. FINISH WALL AROUND NEW DOOR TO PREVIOUS CONDITIONS. 5. THE CONTRACTOR SHALL PATCH ANY WALL PENETRATIONS ABOVE THE CEILING TO ASSURE THAT THE WALL MEETS 2-HOUR FIRE BARRIER STANDARDS. 6. PAINT NOTED WALLS WITH SW6156 RAMIE EGGSHELL OR EQUAL.
- 7. PAINT NOTED WALL TO MATCH EXISTING. 8. PAINT FRAME TO MATCH EXISTING. 9. WOOD SPECIES AND FINISH SHALL MATCH EXISTING DOOR. 10. PROVIDE AND INSTALL FIRE DOOR SIGNAGE IN-01.08.

DOOR REPLACEMENT PLAN

610-10-109 REPLACE VARIOUS DOORS B172/174 (PFI) **VARIOUS** VA NIHCS, Marion, IN Checked 03/12/2012



Scale: 1/4" = 1'-0"

Charles Applewhite

DETAILS, SECTIONS,

ELEVATIONS,

SCHEDULE

FIRE DOORS ARE TO BE EQUIPPED WITH FIRE EXIT HARDWARE. 2. ALL GLAZING SHALL BE LABELED FIRE RESISTANCE-RATED OR FIRE

LABELED FOR BOTH FIRE AND PANIC PROTECTION.

ALL PRIMER AND PAINT SHALL CONTAIN NO VOCs.

WORK AREAS DAILY (I.E. DESKS, FLOORS, WALLS, ETC.).

3. FIRE EXIT HARDWARE SHALL CONSIST OF EXIT DEVICES THAT HAVE BEEN

5. DOOR SIGNAGE SHALL COMPLY WITH VA SIGNAGE CRITERIA AT THE FOLLOWING

FRAME IN MASONRY WALL

FRAME IN MASONRY WALL

FRAMES IN METAL STUD PARTITIONS

STAIN

PAINT

PAINT DOUBLE

LHR

CAULK ALL AROUND

ANCHOR

CAULK ALL AROUND

DOOR SCHEDULE

STEEL

PAINT

PAINT

D3/D4

FRAME FOR

PROTECTION-RATED GLAZING.

6.2. 1 COAT OF BASE

EGRESS DOORS.

EGRESS DOORS.

DOUBLE EGRESS DOOR FRAME

SECTIONS DOUBLE EGRESS DOORS

DOUBLE EGRESS

LED EXIT LIGHT

DOOR AND FRAME SHALL BE

1-1/2 HOUR FIRE RATED

DOOR AND FRAME SHALL BE

1-1/2 HOUR FIRE RATED

DOOR AND FRAME SHALL BE

1-1/2 HOUR FIRE RATED

LOCK MUST ACCEPT A 7-PIN

DOOR AND FRAME SHALL BE

1-1/2 HOUR FIRE RATED

LOCK MUST ACCEPT A 7-PIN

Drawing Number AS101

B174 DOUBLE EGRESS FIRE DOORS